

### Method of order by steel strips for frame saw blades

The order should specify following parameters :

1. Symbol of steel strip ( LT1 - single row steel strip, LT2 - double row steel strip )
2. Length of steel strip - l [mm]
3. Width of steel strip - h [mm]
4. Thickness of steel strip - T [mm]

Exemplary order :

	1	2	3	4
Steel strip LT2	LT2	- 125	- 30	- 3,0

- tools upon request
- tools available from stock