

3.1 ARBOR MILLING CUTTERS FOR MECHANICAL WORKING OF WOOD, WOOD - LIKE MATERIALS AND PLASTICS

Method of order by arbor milling cutters

The order should specify following parameters :

1. Symbol of arbor milling cutter
2. Full diameter - D
3. Width of cutting edge - B
4. Inside diameter - d
5. No. of teeth - z
6. Size of radius and angle or profile number (if available)
7. Grade of cutting edge (from hard metal **HM** or from high speed steel **HSS**)
8. Left or right (if available)

Exemplary order :

a) six - toothed slotting cutter

1 2 3 4 5 7
FT-01 - 80 - 20 - 30 - 6 - HM

b) formed profile cutter

1 2 3 4 5 6 7 8
FPA-03.01 - 125 - 16 - 30 - 4 - R3 - HM - right

- tools upon request
- tools available from stock

ATTENTION - we make also :

1. Regeneration of arbor milling cutters.
2. Sharpening of arbor milling cutters.
3. Special arbor milling cutters for individual order after mutual agreements.