



3.4 FORMED PROFILE CUTTERS

FPA-01.01 HM FPA-01.02 HSS

Formed profile cutters with HM or HSS cutting edges



R	D	B	d	z	n max	L	P
3	100	8	30	4	10.000	o	o
4		9	30	4	10.000	o	o
5		10	30	4	10.000	o	o
6		11	30	4	10.000	o	o
8		13	30	4	10.000	o	o
10		15	30	4	10.000	o	o
12		17	30	4	10.000	o	o
3	125	8	30	4	9.000	o	o
4		9	30	4	9.000	o	o
5		10	30	4	9.000	o	o
6		11	30	4	9.000	o	o
8		13	30	4	9.000	o	o
10		15	30	4	9.000	o	o
12		17	30	4	9.000	o	o
15		20	30	4	9.000	o	o
20		25	30	4	9.000	o	o
4	140	9	30	4	8.000	o	o
5		10	30	4	8.000	o	o
6		11	30	4	8.000	o	o
8		13	30	4	8.000	o	o
10		15	30	4	8.000	o	o
12		17	30	4	8.000	o	o
15		20	30	4	8.000	o	o
20		25	30	4	8.000	o	o
25		30	30	4	8.000	o	o
5	160	10	30	4	6.500	o	o
8		11	30	4	6.500	o	o
9		13	30	4	6.500	o	o
10		15	30	4	6.500	o	o
12		17	30	4	6.500	o	o
15		20	30	4	6.500	o	o
20		25	30	4	6.500	o	o
25		30	30	4	6.500	o	o



FPA-02.01 HM
FPA-02.02 HSS

Formed profile cutters with HM or HSS cutting edges


R	D	B	d	z	n max	L	R
according to order	100	10	30	4	10.000	o	o
		15	30	4	10.000	o	o
		20	30	4	10.000	o	o
		25	30	4	10.000	o	o
		30	30	4	10.000	o	o
		35	30	4	10.000	o	o
		40	30	4	10.000	o	o
		45	30	4	10.000	o	o
	125	10	30	4	9.000	o	o
		15	30	4	9.000	o	o
		20	30	4	9.000	o	o
		25	30	4	9.000	o	o
		30	30	4	9.000	o	o
		35	30	4	9.000	o	o
		40	30	4	9.000	o	o
		45	30	4	9.000	o	o
	140	15	30	4	8.000	o	o
		20	30	4	8.000	o	o
		25	30	4	8.000	o	o
		30	30	4	8.000	o	o
		35	30	4	8.000	o	o
		40	30	4	8.000	o	o
		45	30	4	8.000	o	o
	160	15	30	4	6.500	o	o
		20	30	4	6.500	o	o
		25	30	4	6.500	o	o
		30	30	4	6.500	o	o
		35	30	4	6.500	o	o
		40	30	4	6.500	o	o
		45	30	4	6.500	o	o



ARBOR MILLING CUTTERS

FPA-03.01 HM
FPA-03.02 HSS


Formed profile cutters with HM or HSS cutting edges



R	D	B	d	z	n max	o ●
3	100	16	30	4	10.000	o
4		18	30	4	10.000	o
5		20	30	4	10.000	o
6		22	30	4	10.000	o
8		26	30	4	10.000	o
10		30	30	4	10.000	o
12		34	30	4	10.000	o
3	125	16	30	4	9.000	o
4		18	30	4	9.000	o
5		20	30	4	9.000	o
6		22	30	4	9.000	o
8		26	30	4	9.000	o
10		30	30	4	9.000	o
12		34	30	4	9.000	o
15		40	30	4	9.000	o
20		50	30	4	9.000	o
3	140	16	30	4	8.000	o
4		18	30	4	8.000	o
5		20	30	4	8.000	o
6		22	30	4	8.000	o
8		26	30	4	8.000	o
10		30	30	4	8.000	o
12		34	30	4	8.000	o
15		40	30	4	8.000	o
20		50	30	4	8.000	o

FPA-04.01 HM
FPA-04.02 HSS

Formed profile cutters with HM or HSS cutting edges




R	D	B	d	z	n max	o ●
according to order	100	25	30	4	10.000	o
		30	30	4	10.000	o
		35	30	4	10.000	o
		40	30	4	10.000	o
		45	30	4	10.000	o
		50	30	4	10.000	o
	125	25	30	4	9.000	o
		30	30	4	9.000	o
		35	30	4	9.000	o
		40	30	4	9.000	o
		45	30	4	9.000	o
	140	25	30	4	8.000	o
		30	30	4	8.000	o
		35	30	4	8.000	o
		40	30	4	8.000	o
		45	30	4	8.000	o
		50	30	4	8.000	o

ARBOR MILLING CUTTERS

FPA-05.01 HM
FPA-05.02 HSS

Formed profile cutters with HM or HSS cutting edges




R	D	B	d	z	n max	o ●
3	100	6	30	4	10.000	o
4		8	30	4	10.000	o
5		10	30	4	10.000	o
6		12	30	4	10.000	o
8		16	30	4	10.000	o
10		20	30	4	10.000	o
12		24	30	4	10.000	o
3	125	6	30	4	9.000	o
4		8	30	4	9.000	o
5		10	30	4	9.000	o
6		12	30	4	9.000	o
8		16	30	4	9.000	o
10		20	30	4	9.000	o
12		24	30	4	9.000	o
15		30	30	4	9.000	o
5	140	10	30	4	8.000	o
10		20	30	4	8.000	o
15		30	30	4	8.000	o
20		40	30	4	8.000	o
10	160	20	30	4	6.500	o
12		24	30	4	6.500	o
15		30	30	4	6.500	o
20		40	30	4	6.500	o
25		50	30	4	6.500	o

FPA-06.01 HM
FPA-06.02 HSS

Formed profile cutters with HM or HSS cutting edges


R	D	B	d	z	n max	L	R
according to order	100	10	30	4	10.000	o	o
		15	30	4	10.000	o	o
		20	30	4	10.000	o	o
		25	30	4	10.000	o	o
		30	30	4	10.000	o	o
		35	30	4	10.000	o	o
		40	30	4	10.000	o	o
	125	10	30	4	9.000	o	o
		15	30	4	9.000	o	o
		20	30	4	9.000	o	o
		25	30	4	9.000	o	o
		30	30	4	9.000	o	o
		35	30	4	9.000	o	o
		40	30	4	9.000	o	o
	140	15	30	4	8.000	o	o
		20	30	4	8.000	o	o
		25	30	4	8.000	o	o
		30	30	4	8.000	o	o
		35	30	4	8.000	o	o
		40	30	4	8.000	o	o



ARBOR MILLING CUTTERS

FPA-07.01 HM
FPA-07.02 HSS

Formed profile cutters with HM or HSS cutting edges





α°	D	B	d	z	n max	o ●
according to order	100	10	30	4	10.000	o
		15	30	4	10.000	o
		20	30	4	10.000	o
	125	15	30	4	9.000	o
		20	30	4	9.000	o
		25	30	4	9.000	o
		30	30	4	9.000	o
	140	20	30	4	8.000	o
		25	30	4	8.000	o
		30	30	4	8.000	o
		40	30	4	8.000	o
	160	25	30	4	6.500	o
		30	30	4	6.500	o
		40	30	4	6.500	o
		50	30	4	6.500	o

FPA-08.01 HM
FPA-08.02 HSS

Formed profile cutters with HM or HSS cutting edges

α°	D	B	d	z	L	R
45°	125	25	30	4	•	•



FPB-01.01 HM
FPB-01.02 HSS

Formed profile cutters with HM or HSS cutting edges

R	D	B	d	z	n max	o •
4	125	28	30	4	9.000	o
5	125	32	30	4	9.000	o
6	125	36	30	4	9.000	o
8	125	44	30	4	9.000	o

