


**Chamfer breaking tips**

**PW-09**

Dimensions in mm				Hardness	○ ●
B	H	T	R		
16	12	5	-	N	○



**PW-10**

Dimensions in mm				Hardness	○ ●
B	H	T	R		
16	22	5	1,0	N	○
16	22	5	1,5	N	○
16	22	5	2,0	N	○
16	22	5	2,5	N	○
16	22	5	3,0	N	○
16	22	5	5,0	N	○
16	22	5	6,0	N	○

