

### 7.3 PCD SHANK CUTTERS

D	L1	d	L2	L3	z	L	R
10	25	12	40	75	1 + 1	o	o
12	25	12	40	75	1 + 1	o	o
12	35	12	40	85	1 + 1	o	o
14	25	16	50	85	1 + 1	o	o
16	25	16	50	95	1 + 1	o	●
16	35	16	50	95	1 + 1	o	o
16	43	16	50	103	1 + 1	o	o
18	25	16	50	85	1 + 1	o	o
18	35	16	50	96	1 + 1	o	●
18	43	20	50	103	1 + 1	o	●
20	25	20	50	85	1 + 1	o	o
20	35	20	50	95	1 + 1	o	o
20	43	20	50	103	1 + 1	o	o
20	52	20	50	112	1 + 1	o	o

